

BorgWarner IAM

Core Criteria

BorgWarner IAM Team

Version: 2018 / 01



Acceptance criteria for Turbos


- Cores shall be returned in the original packaging, all protection caps and covers should be used to protect the core. BorgWarner will only accept and credit surcharges against returned old cores from Genuine / Original turbocharger manufacturers. Please check our Reman offers list for guidance as to what turbocharger part numbers we will accept.
- The turbo should not be dismantled, or have any broken connecting Flanges or show signs of significant corrosion. For Turbochargers that have missing parts e.g. Brackets / Actuators, but which are in good conditions and fulfills the other requirements, BorgWarner will offer partial acceptance of 50% (Grade B) of the surcharge value.
- Each returned core is visually inspected according to the core criteria and the cross reference list, and graded in “A” or “B” or “C” quality
 - A = 100%; B = 50%; C = Rejected = 0% of core values

Acceptance criteria for Turbos

Rejected



Broken flanges / interfaces



Unidentifiable



Significant corrosion

Acceptance criteria for EGR valves

- Cores shall be returned in the original packaging, all protection caps and covers should be used to protect the core. BorgWarner will only accept and credit surcharges against returned old cores from Genuine / Original EGR valve manufacturers. Please check our Reman offers list for guidance as to what EGR valve numbers we will accept
- The EGR valves should not be dismantled, or have any broken connecting Flanges or plastic parts. For EGR valves that have missing parts e.g. cooler / actuators, but which are in good conditions and fulfills the other requirements, BorgWarner will offer partial acceptance of 50% (Grade B) of the surcharge value.
- Each returned core is visually inspected according to the core criteria and the cross reference list, and graded in “A” or “B” or “C” quality
 - A = 100%; B = 50%; C = Rejected = 0% of core values

Acceptance criteria for EGR valves

Rejected



Broken housing/casting



Missing motor/solenoid



Dismantled

Reduced
50%



Component missing



Cracked or damaged plastic parts



Cooler missing

BorgWarner Global Aftermarket
offering OE Quality remanufactured
products to service older vehicles



Thank you!



Combustion



Hybrid



Electric